

Special Projects Division 14450 N.E. 29th Pt. Suito 113 Bellevan WA 98007 Phone (425) 881-4000 (425) 881-3642

March 5, 2001

Turner Construction Company performed the following items during the earthquake repair to get the building opened at the Dexter Horton Building.

- Inspected all plaster walls and ceilings for damage. 1.
- 2. Removed plaster at areas that separated from the substrate material.
- Inspected all fire doors and repaired five that were not closing properly. 3. Removed or covered broken windows.
- 4. Removed all debris and rubble from all floors and stairwells. 5.
- 6 Repaired and/or replaced 4 hr. fire separation walls.
- 7 Patched 2 hr. fire separations walls.
- Inspected all public restrooms. 8 Provided final cleaning of Building offices, common areas, and stairwells
- 9.
- 10. Inspected and tested fire alarm system.
- Inspected and tested fire sprinkler system. 11. 12 Built and maintained public barricades at street locations.
 - 13. Worked with Pinnacle Realty management on coordinating their emergency repair crews.
 - Attended all meetings with structural engineers. 14.
 - 15 Performed random bulk asbestos testing for the plaster material. Performed random quality testing throughout the building. 16

If you should have any questions my phone number is (206) 391-3218

ER CONSTRUCTION COMPANY

Project Manager